

VEHICLE IMAGE REPORT

Owner: **TABCO LLC** Contact: **(678) 632-2886** Inspector: **Tony R** Location: **Roswell, GA**

Year:	2008	Color:	White	Plate:	CLK6838	Status:	Damaged
Make:	Suzuki	Mileage:	103,414	State:	GA	Condition:	Average
Model:	Grand Vitara	Engine:	V6	VIN#:	JS3TE941X84104619	Check Engine:	No



Picture 1: Front Left Corner



Picture 2: Front Right Corner



Picture 3: Odometer



Picture 4: VIN Sticker